



575

## NOTES:

- 1. N.C. MEANS "NO CONNECTION."
- 2. LINES MARKED N.C. MUST BE CAPPED TO PREVENT INADVERTANT CONNECTION.
- 3. A 120V LOAD CAN USE A 1 PHASE OR A 3 PHASE SUPPLY.
- 4. A 3 PHASE LOAD REQUIRES A 3 PHASE SUPPLY.
- 5. REFER TO DRIVE NAMEPLATE FOR 3 PHASE VOLTAGE OUTPUT RATING.

SIZE:

THIS DOCUMENT IS A COPY AND IS NOT THE SOURCE DOCUMENT. INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. THE INFORMATION CONTAINED HEREIN IS COPYRIGHTED BY HAROLD BECK AND SONS, INC. CHANGES TO THE DOCUMENT ARE PROHIBITED. CONTACT A BECK SALES ENGINEER IF A CERTIFIED DRAWING IS REQUIRED.

## **HAROLD BECK & SONS INC**

NEWTOWN INDUSTRIAL COMMONS

NEWTOWN, PENNSYLVANIA 18940 USA

TITLE:

## WIRING DIAGRAM GROUP 22 TRANSFORMER 1 PHASE OR 3 PHASE LOAD

DRAWN: GMD 8/29/07	SCALE: NONE	DRAWING NO:	REV:
CHECKED: CHH 10/15/07		17-2200-040	C
APPROVED: JHM 10/15/07		SHEET NO. 1 OF 1	